AES Indiana Attachment AKH-6(C)
Page 29 of 49



Photograph 5, Damaged STG Turbine (HP section)




Photograph 6, Damaged STG Blade Edges

PUBLIC VERSION




Photograph 7, Missing Blade STG HP Section




Photograph 8, STG Casing Bolts

Cause No. 38703 FAC 133S1 AES Indiana Attachment AKH-6(C) Page 31 of 49



Photograph 9, Eagle Valley Operator Control Station



Photograph 9, Toshiba Alarm Viewer

PUBLIC VERSION

Supporting Figures




Figure 1, Regression analysis of HP Exhaust Temperature cooling curve




Figure 2, Regression analysis of HP Inner Upper Casing cooling curve




Figure 3, Regression analysis of HP Inner Lower Casing cooling curve

Cause No. 38703 FAC 133S1 AES Indiana Attachment AKH-6(C) Page 33 of 49




Figure 4, Toshiba HP Turbine Exhaust Temperature Limitation Curve

PUBLIC VERSION




Figure 5, Toshiba Cold Startup design curves




Figure 6, Simplistic overview of Bypass Steam System




Figure 7, Operator Display for Steam Turbine Overview




Figure 8, Operator Display for Turbine Bypass System